



STATE OF DELAWARE

ASBESTOS INSPECTION FORM

ROOF REPLACEMENT PROJECT



THIS SECTION TO BE FILLED OUT BY THE OWNER OF THE OWNER'S OFFICIAL REPRESENTATIVE

FACILITY INFORMATION			
Facility Address: Delaware Technical & Community College - Wilmington Campus - East Building			
City: Wilmington	County: New Castle	State: DE	Zip: 19801
Owner's Name: Delaware Technical & Community College		Phone: 302-857-1654	
Owner's Address: 333 Shipley Street			
City: Wilmington	County: New Castle	State: DE	Zip: 19801
Owner's Contact: Mark A. DeVore		Owner's Phone: 302-857-1654	

THIS SECTION TO BE FILLED OUT BY CERTIFIED PROFESSIONAL SERVICE FIRM

Professional Service Firm: Harvard Environmental, Inc.			
Address: 760 Pulaski Highway			
City: Bear	County: New Castle	State: DE	Zip: 19701
Inspector's Name: Jeffrey Demicco		Phone Number: 302-326-2333	
Inspector Certification #: ACC-0219-6-002		Professional Service Firm Certification #: PS-054	
Type of Inspection: Renovations <input checked="" type="checkbox"/> Demolition <input type="checkbox"/>		Date(s) Of Inspection: 11/15/19	
Is Asbestos Material Present: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>			
<p>This certification signed by the Inspection Firm, serves that the above-mentioned property or part thereof has been inspected for asbestos containing materials in accordance with the State of Delaware Regulations Governing the Control of Air Pollution. Regulation #21 Section 10.</p> <p>Comments: The inspection was specific to the roofing materials of the East Building of the Wilmington (George) Campus. No asbestos containing roofing materials were found during the inspection. All samples were analyzed under PLM Method. Reference Analytical Report dated 1/10/20, Project # 21152, issued by Harvard Environmental, Inc.</p>			
Signature:		Date: 1/10/20	
Print Name: Michael Sanders		Title: Project Representative	

THIS SECTION TO BE FILLED OUT BY OWNER OR OPERATOR

<p>If RACM Is Present and Will Be Disturbed; Name of Abatement Contractor: Not Applicable</p>
--



STATE OF DELAWARE

ASBESTOS INSPECTION FORM

CHILD DEVELOPMENT CENTER – ROOF INSPECTION



THIS SECTION TO BE FILLED OUT BY THE OWNER OF THE OWNER'S OFFICIAL REPRESENTATIVE

FACILITY INFORMATION			
Facility Address: 2 nd and Shipley Street – Child Development Center			
City: Wilmington	County: New Castle	State: DE	Zip: 19801
Owner's Name: Delaware Technical Community College		Phone: 302-857-1654	
Owner's Address: PO Box 897			
City: Dover	County: Kent	State: DE	Zip: 19903
Owner's Contact: Mark A. DeVore		Owner's Phone: 302-857-1654	

THIS SECTION TO BE FILLED OUT BY CERTIFIED PROFESSIONAL SERVICE FIRM

Professional Service Firm: Harvard Environmental, Inc.			
Address: 760 Pulaski Highway			
City: Bear	County: New Castle	State: DE	Zip: 19701
Inspector's Name: Ron Knight		Phone Number: 302-326-2333	
Inspector Certification # : ACC-0619-6-007		Professional Service Firm Certification # : PS-054	
Type Of Inspection: Renovations <input checked="" type="checkbox"/> Demolition <input type="checkbox"/>		Date(s) Of Inspection: 12/19/19	
Is Asbestos Material Present: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>			
<p>This certification signed by the Inspection Firm, serves that the above-mentioned property or part thereof has been inspected for asbestos containing materials in accordance with the State of Delaware Regulations Governing the Control of Air Pollution. Regulation #21 Section 10.</p> <p>Comments: Roofing materials were sampled for asbestos and analyzed under PLM. No asbestos containing materials were found in the analyses. Reference Report dated 1/10/20, Project 21206, issued by Harvard Environmental, Inc. 302-326-2333.</p>			
Signature:		Date: 1/10/20	
Print Name: Michael Sanders		Title: Project Representative	

THIS SECTION TO BE FILLED OUT BY OWNER OR OPERATOR

<p>If RACM Is Present And Will Be Disturbed; Name Of Abatement Contractor: Not Applicable</p>
--